

## WORLD RESOURCES COMPANY

Form FM-M01

	REC	CYCLABLE MA	TERIAL PRO	OFILE	EXHIBIT A
A. Generator Infor	mation:		Company I.D. Number: W2149A3		
Generator:     Address:	Alaskan Copper Works P. O. Box 3546		4. Material EPA	Waste Code:	D007
	Seattle, WA 981:	24	5. Generator's E	EPA I.D. Number:	WAD980738546
3. Contact: Mr. Gerald Thomp				State I.D. Number:	
B. Recyclable Mate	Environmental Ass				
1 Color(o)	· · · · · · · · · · · · · · · · · · ·	6. Texture similar to:	7. Appearance	9. Free Liquids	
Blace	<u> </u>	X Wet Clay	X Homogeneous	(EPA SW 846, Method 9095)	Present:  X No Yes
2. Odor:		Dry Clay	Bilayered	10. Debris Present	11. Reactivity
X None  Mile	· ·	Powder	1	X No	X Not Reactive
Description of Odor:		Other	Multilayered	Yes	Reactive
3. Moisture:		8. Organic Vapors	· · · · · · · · · · · · · · · · · · ·	12. Radionuclide	es en la
X Wet Damp Dry		X Not Present Present		(ASTM D5928-96)	,
Percent Solids: 53.80		If present, identify compounds and amount (ppm wet):		X Not Detected	d Detected
(EPA SW 846,	5. Ignitability (40 CFR §261.21)			13. Cyanide Gas HCN:	
Method 9040/9045)	X Pass			X Not Detected	<b>.</b>
pH: <u>7.62</u>	☐ Fail	X Pass	Fail	Detected	ppm
C. Analytical Data:		(Content on a dry weigh	nt basis in ppm or %)		PP.
Constitu	ient *	Content	Constit	uent *	Content
1. Aluminum <sup>1</sup>	Al	99450 ppm	19. Magnesiur	m <sup>2</sup> Mg	2651 ppm
2. Antimony <sup>1</sup>	Sb	316 ppm	20. Manganes		6049 ppm
3. Arsenic 1	As	75.0 ppm	21. Mercury <sup>3</sup>	Hg <	
4. Barium <sup>1</sup>	Ba	6 ppm	22. Nickel <sup>1</sup>	Ni	61140 ppm
5. Beryllium <sup>1</sup>	Be	< 0.30 ppm	23. Selenium <sup>1</sup>	Se _<	69.0 ppm
6. Bismuth 1	Bi	< 10 ppm	24. Silver 1	Ag<	: 4 ppm
7. Cadmium <sup>1</sup>	Cd	50.0 ppm	25. Thallium 4	TI <u></u> ≤	: 116.0 ppm
8. Calcium <sup>1</sup>	Ca	<u>1016 ppm</u>	26. Tin <sup>1</sup>	Sn	110 ppm
9. Chloride <sup>7</sup>	Cl⁻ 5	0.07 %	27. Zinc <sup>1</sup>	Zn	<u>1631 ppm</u>
10. Chromium, Hex	4	71.0 ppm			
11. Chromium, Tota		66320 ppm	Analytical Procedure R	References:	
12. Cobalt <sup>1</sup> Co		756 ppm	<sup>1</sup> EPA Method SW846 3050 / 6010 (Digestion / Analysis)		
15. Copper 2 EPA Method SW846 3050 / 7450 or 6010 (Digestion / Analysis)					/ Analysis)
14. Cyanide, Amena		0 ppm	3 EPA Method SW846 3050 / Hydride generation (Digestion / Analysis) 4 EPA Method SW846 3050 / 7840 or 6010 (Digestion / Analysis)		
15. Cyanide, Total <sup>6</sup> 16. Fluoride <sup>7</sup>	5 EPA Method SW846 1311 or 3060 / 7196 (Extraction / Analysis)				
17. Iron <sup>1</sup>					
	Fe 	<u> </u>	HNO3 or H2O2 / EPA Meth	od SW846 9056 (Digestion	ı / Analysis)
18. Lead <sup>1</sup> D. Certification:	Pb	< 17 ppm			
	information submit	tted in this profile is comp	lete and accurate to th	e best of my knowle	edge and belief
Signed:	white		Date:	06/22/2001	
Title:	Laborato	ry Manager			e e e e e e e e e e e e e e e e e e e
ZF004\\F21			Copyright © 198	9 World Resources Comp	any revised 09/20/00

8113 West Sherman Street Phoenix, AZ 85043-3000

Tel: 602.233.9166 Fax: 623.936.9164

June 22, 2001

Mr. Gerald Thompson Environmental Assistant Alaskan Copper Works P. O. Box 3546 Seattle, WA 98124

Dear Mr. Thompson:

Enclosed for your records is a completed "RECYCLABLE MATERIAL PROFILE" (profile sheet) for the material generated at your facility. In accordance with the recycling Agreement with your company, World Resources Company (WRC) provides a completed profile sheet each contract year.

The concentration of metals reported on the profile sheet is the total concentration of each metal on a dry basis. The recyclable material is prepared for analysis by first grid-sampling and then drying the selected sample in the laboratory oven at 103°-105° centigrade in order to obtain a homogeneous dry sample (Standard Methods For The Examination of Water and Wastewater, 15th Edition, published by the American Public Health Association 1980, Method 209A "Total Residue at 103°-105° centigrade"). Therefore, these results are generally higher than the concentrations of your material as it leaves your facility. You should multiply these dry concentrations by the decimal form of your percent solids (i.e. 50.0% = 0.50) to obtain the concentration of your material as it leaves your plant.

WRC appreciates your business and looks forward to a long and mutually beneficial recycling relationship. Please feel free to call me with any questions you may have regarding the enclosed profile sheet. Thank you for your interest in recycling.

Sincerely,

World Resources Company

John M. Richmond

Laboratory Manager

